








OPTIONAL ACCESSORIES HANDHELD PARTICLE COUNTERS

Part #	Description	GT-321	GT-521	GT-526	AEROCET 531	804	BT-637
	9801 or 80530 Flow Meter (Pictured w/Aerocet 531)	P/N 9801	P/N 9801	P/N 9801	P/N 9801	P/N 80530	P/N 9801
	G3115 Portable Printer	NO	YES	YES	YES	NO	YES
	750509 Printer Paper						
	G3120 Temperature / Humidity Sensor (pictured w/ GT-521)	NO	YES	YES	YES	NO	YES
	550067 Serial to USB Adapter	YES	YES	YES	YES	NO	NO
	8517 Carrying Case	INCL	INCL	INCL	INCL	YES	NO
	80450 Protective Boot	N/A	N/A	N/A	N/A	YES	N/A
	80846 Zero Filter Kit	INCL	INCL	INCL	INCL	YES	INCL